



PAT-04 Activation Instructions

- Please go to tracking.gpsit.com to create an account and to register the device.
- We recommend connecting the device to a 5V 1A (cellphone) adapter through the supplied magnet USB cable for 10 hours charging to make sure the battery is fully charged.
- Once the device is charged, registered, and in your account it is ready to use.
- The tracking setting is set to 4 minutes on movement and 24 hours when not moving. There are other features that can be used. Please see online portal for instructions.

sales@gpsit.com
[888-464-7748](tel:888-464-7748)

105 W 35TH ST STE L, NATIONAL CITY, CA 91950